

US EPA ARCHIVE DOCUMENT

UNIT LOG	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 10/13/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Melinda Leutke, Planning Section Chief		6. Operational Period 0700, 10/11/2012 – 0700, 10/18/2012
7. Personnel Roster Assigned			
Name		ICS Position	Home Base
Matthew Haak		Situation Unit Leader	Houston, TX
8. Activity Log			
Time	Major Events		
0745	<ul style="list-style-type: none"> Arrived at C0.4 boat launch. No boat was at the launch. While waiting on the boat I observed ribbons of sheen with tar globs floating past the C0.4 boat launch. 		
8:50	<ul style="list-style-type: none"> Boat arrived, heavy rain began falling. MP5.63 LDB no sheen observed Ceresco Dam Control Point Boom observed tiny ribbons of sheen collecting along the control point boom. MP5.55 RDB no sheen observed. MP5.0 RDB sheen and tar glob observed. MP4.5 no sheen observed. 		
1100	Finish up inspections at C0.4 boat launch. Return to ICP.		
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START			